date of	first name(s) /	surname	sex a	ge locatio	n count	v country	grade	primary railway company	any other companies	time of	nature of	precise details of	type of	details of accident	length of time employed	other people	responsibility/ cause	rules mentioned	recommendations made	booked tim		tor other notes	document title	document sub-title	document	document	page
accident	initial(s)					,,		responsibl for locatio	e involved? n	accident	casualty	injury	accident		employed by company	mentioned	,			hours d	ty inspe				reference	date	number
1900 May 17	William	Burley	м з	30 Breco goods y	rd Brecknock	shire Wales	Goods porte	Brecon and er Merthyr Railway		10:15	Fatal	Knocked down and run over with fatal consequences	Shunting	Burley for some cause, got foul of the "straight" road, and while in that position he was knocked down and run over by 12 wagons which had been shunted back by Cambrian's Company guard, Thomas Lewis		Thomas Lewis, guard	I am of the opinion that owing to the slight curve in the sidings and the narrow space between the "goods" and "straight" roads, he, for the moment forgetting tat the Cambrian's engine was at work and got foul of the "straight" road. In the circumstances I am of the mishap was misadventure		For safety I recommend that the engine shed, should be removed and the sidings remodelled. Otherwise the traffic should so be arranged to prevent more than one engine be working in these sidings at the same time		45 A.F	d	Returns of Accidents and Casualties as reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending 30 June 1900	Appendix B. Reports of the Sub-Inspectors A Ford and JJ Homby on accidents to Railway Servants and other Persons employed on railway premises	Cd.322	1900 Jun 30	114-115
1903 Apr 24	John	Watkins	м	Pontsti	II Brecknock	shire Wales	Lad porter	Brecon and Merthyr Railway		14:50	Injury: Contusion(s)	Bruising to left foot	Whilst on railway property	He volunteered to help turn an engine on a turntable. His left foot was caught between a projecting rail and the ground		Thomas Price, Driver	Unsatisfactory condition of turntable. Projecting rails are a source of danger when the table is turned in one direction. The table is too week to take the weight of modern engines.		same time  Strengthen turntable and remove projecting rails, issue instructions that the turntable should only be moved in one direction The levers for pushing the table should be firmly secured to the table. A lamp should be provided for night time operation. The turntable should be inspected reputably.	01	00 JHAm	tage	Returns of Accidents and Casualities as reported to the Board of Trade by the several railway companies in the United langdom during the three months ending 30 June 1903	Appendix B. Reports of the Assistant Inspecting Officers of Railways on accidents to railway servants and other persons employed on railway premises	Cd.1733	1903 Jun 30	85
1905 Sep 5	D	Watkins	М	Devyno	k Brecknock	shire Wales	Fencer	Neath and Brecon Railwo	zy	17:00	Fatal		Whilst about	Walking on the line over an underbridge, Watkins failed to see or hear the train he was due to catch approaching and was struck by the buffer of the engine sustaining fatal injuries		Driver Walter of the offending engine	Although Watkins was slightly deaf, the accident is due to his own want of care. He knew the train was due but walked onto the bridge without checking if it was safe to do so.		inspected regularly.  Where men are expected to walk the lines for their work they should have good sight and hearing and the Company should be asked to see this is the case for the men in this employ.	01	30 JPS	ain neglecting to sound the whistle a	Returns of Accidents and Casualties as reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending 30 Contember 1905	Appendix B. Reports of the Assistant Inspecting Officers of Railways on accidents to railway servants and other persons employed on railway premises	Cd.2827	1905 Sep 30	119
1906 Jun 27	Thomas	Morris	М	Marte Tunne Rhyad		shire Wales	Ganger	Cambrian Railways		09:30	Fatal	Morris was struck by a moving engine	Whilst about the track	Morris was removing the wheels of a trolley when he was struck by the engine		William Evans, platelayer; Price Williams; platelayer; Edwin Jones, driver	The severe gradient, curvature and state of the rails, rendered strict compliance with the rules necessary	250		0-	15 J H Arm	tage	September 1905 Returns of Accidents and Casualities as reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending 30 land 1905	employed on railway premises	Cd.3220	1906 Jun 30	79-80
1909 Feb 4	Thomas	Hardwick	М	Breco	Brecknock	shire Wales	Goods guar	Brecon and Merthyr Railway	Midland Railway	12:45	Fatal		Caught between vehicles	Horsley was to shunt 11 wagons into a sdg. Hardwick went there ready to couple them to 4 other wagons. He was in front of a wagon's buffer as the shunted wagons arrived and he was crushed between vehicles		W Horsley, brakesman; J Wilding warehouseman	The accident was attributed to Hardwick's lack of care. He asked Wilding how many wagons were bound for Swansea while he stood foul of the wagon. He never saw the wagons being shunted into the road.			01	35 JPS	ain	Jane 1906  Summary of Accidents and Casualties reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending during the three months ending 11 March 1909	Appendix B. Reports of the Assistant Inspecting Officers of Railways on accidents to railway servants and other persons employed on railway premises	Cd.4826	1909 Mar 31	62
1910 Oct 5	GН	Lewis	М	Builth W	ells Brecknock	shire Wales	Goods porte	Cambrian er Railways		18:30	Fatal	Lewis was killed after falling from a wagon	handling	Lewis was sheeting a wagon of wool. Shunterman Morgan loose shunted two wagons into the shed where Lewis was working. About half an hour later Lewis' body was found by Phillips when he went to label the wagons.	1	John Phillips, Warehouseman; Morgan, Shunterman	Morgan was held responsible for failing to give warning of the movement of wagons into the shed. He should have determined whether anyone was working on the wagons in the shed before shunting the wagons.	112 (a)		1	00 JPS	ain	Summary of Accidents and Casualties reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending during the three months ending 31	Appendix B. Reports of the Assistant Inspecting Officers of Railways on accidents to railway servants and other persons employed on railway premises	Cd.5688	1910 Dec 31	41-42
1910 Nov 28	Thomas	Evans	м	41 Brecon Er Shed	gine Brecknock	shire Wales	Engine drive	Brecon and er Merthyr Railway		05:25	Fatal		Workshops	After oiling his engine Evans asked Lewis to take the engine out of the shed but whilst getting on to the footplate he slipped and was caught between the engine and the shed door		F Lewis, fireman	The accident was attributed to Evan's error of judgement in thinking he could get on to the footplate before the steps he was on reached the shed door			10:00 0	30 JJ Ho	iby	December 1930  Summary of Accidents and Casualities reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending 31  December 1910  Ballway Accidents	Appendix C. Reports of Sub-Inspectors IJ Hornby, A Ford and C. Campbell on accidents to Railway Servants and other Persons employed on railway premises	Cd.5688	1910 Dec 31	71
1911 Oct 24	David	Jenkins	М	Pontsam -	Cefn Brecknock	shire Wales	Ganger	Brecon and Merthyr and London and North Weste Joint Railway	m	10:15	Fatal		Whilst about the track	While attempting to retrieve pair of wheels of platelayers' lorry from tracks, it was struck by engine of approaching train, knocking him down		; ; ;	Extraordinary want of care by victim			0	15 JHAm	tage	Railway Accidents. Summary of Accidents and Casualities reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending 31 December 1911	Appendix B. Reports of the Assistant Inspecting Officers of Railways on Accidents to Railway Servants and other Persons employed on railway premises	Cd. 6174	1911 Dec 31	82-83
1911 Dec 16	James	Brown	м :	34 Beaufo	t Brecknock	shire Wales	Warehousen n	London and na North Weste Railway	m	12:30	Injury: Other- see 'Precise details of injury' field	injured	Shunting	Whilst inserting a sprag into the spokes of a stationary wagon wheel, he dropped the sprag on to his leg			The cause was misadventure as he was carrying out his duties correctly			12:00 0	00 JJHo	lay	Railway Accidents. Summary of Accidents and Casualties reported to the Board of Trade by the several allway companies in the United Kingdom during the three months ending 31 December 1911	Appendix C. Reports of the Sub-Inspecting Officers of Railways on Accidents to Railway Servants and other persons employed on railway premises	Cu. 01/4	1911 Dec 31	131
1911 Dec 4	Daniel	Evans	м (	66 Cray	Brecknock	shire Wales	Ganger	Neath and Brecon Railwa	77	09:15	Fatal		property	He had to move a cattle wagon which was standing on a gradient with its single brake on the lower end, alongside the dock wall. He released the brake to allow it to run forward but it moved faster than he expected, trapping him against the dock wall	į.	· · · · · ·	The accident was due to misadventure			10:00 0	30 JJHo		Railway Accidents. Summary of Accidents and Casualities reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending 31 December 1911 Railway Accidents. Summary of Accidents	Appendix C. Reports of the Sub-Inspecting Officers of Railways on Accidents to Railway Servants and other persons employed on railway premises	Cd. 6174	1911 Dec 31	139
1912 Dec 21	George	Simmonds	м :	Breco 30 locomot yard	re Brecknock	shire Wales	Shed forema	Brecon and an Merthyr Railway		11:00		Right thigh and left leg injured	Working trains	Fell to the ground when a plank supporting the coal wagon door on which he was standing slipped while coaling an engine	 		Attributed to the dangerous system of working		The Company should prohibit this practice as it is by nearly all Railway Companies	12:00 0	00 JJHo	by	sainway Accidents. Summary of Accidents and Casualties reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending 31 December 1912. Railway Accidents. Summary of Accidents	Officers of Railways on Accidents to Railway Servants and other persons employed on railway premises	Cd. 6819	1912 Dec 31	66-67
1912 Dec 17	Thomas	Evans	м :	37 Talylly	Brecknock:	shire Wales	Warehousen n	na Cambrian Railways	Bargoed Colliery Company	18:05	Contamore	Left side and hip bruised and head cut	Shunting	Knocked down by a passenger train after his shunting pole, which was being used as a brake stick to stop a wagon, fouled the steps of the engine	 		Attributed to disregarding instructions forbidding the use of shunting poles as brake sticks			12:00 0	30 JJ Ho			Appendix C. Reports of the Sub-Inspecting Officers of Railways on Accidents to Railway Servants and other persons employed on railway premises	Cd. 6819	1912 Dec 31	68-69
1913 Feb 19	Daniel	Leonard	м з	Talyllyn, 59 road ar engine r	d Brecknock ad	shire Wales	Coalman	Brecon and Merthyr Railway		15:30	Multiple	Right side and left foot injured	Working trains	The door of a coal wagon was lowered and used as a platform while Leonard was throwing coal. The iron rail supporting the door slipped causing Leonard to fall striking the footstep of the engine.			Dangerous system of working (now discontinued)			11:00 0	10 JJHo	by	and Casualties reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending 31 March 1913 Railway Acridents Summary of Acridents	Officers of Railways on Accidents to Railway Servants and other persons employed on railway premises	Cd. 7038	1913 Mar 31	94
1913 Feb 21	William	Crimmings	м :	19 Breco	Brecknock	shire Wales	Relief firema	Brecon and an Merthyr Railway		12:30	details of injury' field	left hand injured	Working trains	While standing in the ash pit and coupling two wagons, Crimmings rested his hand on the drawbar hook of a wagon. His fingers were caught between the drawbar shoulder and headstock.	ļ 	W Vaughan (Engine Driver)	Want of care by Crimmings			12:00 0	30 JJ Ho	by Coupling poles will be supplied in future	and Casualties reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending 31 March 1913 Railway Accidents. Summary of Accidents		Cd. 7038	1913 Mar 31	94
1913 Mar 25	Arthur	нш	м :	19 Hay, no	ar Brecknock	shire Wales	Labourer	Midland Railway		11:45	injury' field	Forehead slightly injured	Whilst on railway property	Hill lost his balance and fell over the end of a vehicle due to a rebound as it moved.	10 days	Five other labourers.	Inexperience on the part of HII.			11:30 0	45 JJ Ho	by	and Casualties reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending 31 March 1913 Railway Accidents. Summary of Accidents	Appendix C. Reports of the Sub-Inspecting Officers of Railways on Accidents to Railway Servants and other persons employed on railway premises	Cd. 7038	1913 Mar 31	122:123
1913 May 3	Edmund	Lewis	м :	20 Talylly	Brecknock:	shire Wales	Fireman	Brecon and Merthyr Railway		20:15	Injury: Other- see 'Precise details of injury' field	Right eye injured – no details	Working trains	Climbed onto coal in the tender of a moving engine to release a rope and right eye was struck by a goods loading gauge		The loco driver— unnamed	Lewis disregarded the Rule stating that he should not leave the footplate of a moving engine	24 (a)	The company should issue instructions to footplatemen not to leave the footplates of moving locos except in emergency		40 JJ Ho	by	and Casualties reported to the Board of Trade by the several railway companies in the United Kingdom during the three months ending 30 June 1913	Appendix C. Reports of the Sub-Inspecting Officers of Railways on Accidents to Railway Servants and other persons employed on railway premises	Cd. 7144	1913 Jun 30	79-80
1913 Jun 14	George	Williams	М 3	37 Breco	Brecknock	shire Wales	Goods guar	Railway	Railway	20:30	details of injury' field	nose injured – no details	Shunting	Unable to apply brakes to a moving wagon, he tried to stop it by showing his shutting pole through the moving wheel's spokes. This broke the pole and the hook end hit him in the face and nose	į		Williams failed to check the wagon brakes before releasing them				40 JJ Ho	· •	the United Kingdom during the three months ending 30 June 1913 Railway Accidents. Reports by the	Appendix C. Reports of the Sub-Inspecting Officers of Railways on Accidents to Railway Servants and other persons employed on railway premises	1	1913 Jun 30	1
1924 Apr 3	Robert Baden	Pugh	м :	24 Rhosfer tunne	8 Brecknock:	shire Wales	Labourer	London, Midland and Scottish Railway		<u> </u>	Fatal		Whilst about the track	Pugh was walking along the track in a tunnel with his blocket. He was wamed of an oncoming train and stood between his blocked and the train, rather than hying down. The train struck him carrying him out of the tunnel by about 18 yards	<u> </u>		Pughs own want of caution		The wheeling and riding of bicycles along the track should be prohibited		Wm W Coc	nthy e	Inspecting Officers of Railways, Railways Employment Inspectors and Railways Employment Assistant Inspectors of Inquiries into accidents which occurred during the three months ending 30 June 1924 Railway Accidents. Reports by the	Appendix C. Reports of the Sub-Inspecting Officers of Railways on Accidents to Railway Servants and other Persons employed on railway premises		1924 Jun 30	1
1926 Jun 7	John	Wilding	М 3	58 Brecoi goods y		shire Wales	Shunter	Great Weste Railway	m	07:50	Injury: Other- see 'Precise details of injury' field	Chest, shoulder and arm bruised	Shunting	He entered the 4ft way to slacken a screw coupling. Having done so, he stood astride the rail to give a stop signal to the engineman and was caught between the buffers.			it was Wilding's fault for entering the 4ft way whilst the engine was in motion, in contravention of rules.	23 (g)		0:	50 Wm W	rthy	Inspecting Officers of Railways, Railway Employment Inspectors and Railway Employment Assistant Inspectors of Inquiries into accidents which occurred during the three months ending 30 June	Appendix C. Reports of the Sub-Inspecting Officers of Railways on Accidents to Railway Servants and other Persons employed on railway premises		1926 Jun 30	15
1930 Aug 9	Herbert Henry	Price	М 3	Breco 39 Junctio Statio	- Brecknock	shire Wales	Fireman	Great Weste Railway	London, Midland and Scottish Railway (employer)	16:10	Injury: Cut(s) or laceration(s)	Laceration of forehead. Abrasions of shoulder and neck	Working trains	While running light, Price got on top of the tender and was shovelling coal forward, without the knowledge or consent of Summers. He was caught under the chin by telephone wires across the lines and was knocked unconscious on the tender		Summers, engine driver	The wires were only 15 ft above rail level, but Price was still responsible for the accident by unnecessarily going on the tender while the engine was in motion, contrary to the Company's regulations.	Regulation concerning leaving the footplate while an engine is in motion	The telephone wires have now been raised to 18ft 6in above rail level, but I recommend the wires be lifted to span the railway at least 20ft above rail level and the length of the span be reduced by an additional pole	08:00 0	50 Wm W Coc		1926 Railway Accidents, Reports by the Inspecting Officers of Railway, Railway Employment Inspectors and Railway Employment Assistant Inspectors of Inquiries into accidents which occurred during the three months ending 30 September 1930.	Appendix C. Reports of the Sub-Inspecting Officers of Railways on Accidents to Railway Servants and other Persons employed on railway premises		1930 Sep 30	29